

FIAT SERVICE LETTER

SUBJECT: ELECTRONIC IGNITION CONTROL MODULE

VEHICLES: 1979 X1/9 VEHICLES

SERIAL NOS: FROM #98031 TO #102564

CONDITION: Tachometer does not operate.

CAUSE: Possible improper assembly of the ignition electronic control module.

CORRECTION: Inspect the electronic control module to insure the three digit number "029" located on the module face plate, is also stamped on the right side mounting ear of the module assembly. (See illustration.)

If the three digit number on the mounting ear is not "029", the control module must be replaced.

The control module is mounted in the right side upper corner of the engine compartment, underneath a protective cover.

PARTS INFORMATION:

The part number for the electronic control module is #4419628.

WARRANTY INFORMATION

The part and labor expended in performing this repair may be submitted on a regular warranty claim.

The operation number and time allowance are as follows:


| <u>DESCRIPTION</u> | <u>OPERATION NO.</u> | <u>TIME ALLOWANCE</u> |
|-------------------------------|----------------------|-----------------------|
| R & R Ignition Control Module | 551-01-52 | 0.4 hours |

All replaced ignition control modules must be properly tagged and returned with the warranty claim to:

FIAT MOTORS OF NORTH AMERICA, INC.
155 Chestnut Ridge Road
Montvale, New Jersey 07645
Attention: Field Operations

READ, INITIAL AND PASS ON

| Service Manager | Parts Manager | Service Writer | Technician |
|-----------------|---------------|----------------|------------|
| | | | |



NUMBERS MUST
BE THE SAME