

FIAT SERVICE LETTER

SUBJECT: WINDOW REGULATOR

VEHICLES: X1/9

SERIAL #: 56981

CONDITION: Window Mechanism will not operate properly.

CAUSE: Window regulator winding cable either tangled or out of adjustment.

CORRECTION: A new type of window regulator has been installed in vehicles starting with the above mentioned serial number.

The routing of the new regulators' winding cable, which is now longer and more flexible, has been modified in order to improve the operation of the cable mechanism.

The method used in locking the tensioner pulley in place has also been modified with the addition of a metal plate which is secured to the door panel by a self tapping screw.

Enclosed is a diagram illustrating the major difference in the routing of the new and early type window regulators.

PARTS INFORMATION:

The new type of window regulator cannot be installed in vehicles built before the above serial number. The part numbers for the new window regulators are as follows:

Right window regulator - Part #5869750

Left window regulator - Part #5869751

Service Manager	Parts Manager	Service Writer	Technician			