

FIAT SERVICE LETTER

SUBJECT: AIR CONDITIONING BELT - KIT NO. 4752

VEHICLES: 1979 STRADA AND X1/9 MODELS (49 STATE VERSION)

THIS LETTER SUPERSEDES SERVICE LETTER NO. 501-17,
DATED 8/23/79

CONDITION: Slipping of the air conditioning compressor belt

CAUSE: Insufficient wrap of the belt on the compressor pulley

CORRECTION: A modification kit to correct this condition has been made available.
This kit contains

- A new waterpump pulley to facilitate a change in the existing drive belt arrangement
- A new air conditioning belt to drive only the compressor off the crankshaft
- A new belt to drive the waterpump and alternator off the compressor

The installation of the new kit will provide a more parallel belt profile that maximizes belt wrap around the air conditioning compressor and crankshaft pulley, thus eliminating belt slippage.

Installation instructions are attached.

IMPORTANT: Previous idler pulley kit, Part No. 4415, must be removed to install the above mentioned kit.

SERVICE INFORMATION: Until further notice, the water pump modification kit must be installed on all vehicles equipped with Fiat Factory air conditioning presently in your inventory or brought into your dealership for service or repairs.

WARRANTY INFORMATION: Parts and labor expended in performing this modification should be submitted on a regular warranty claim.

READ, INITIAL AND PASS ON

Service Manager	Parts Manager	Service Writer	Technician			