

FIAT SERVICE LETTER

SUBJECT: BOOTS ON STEERING BOX

VEHICLES: X1/9 MODELS
128 MODELS
131 MODELS

CONDITION: Twisting of steering box boots when the rods are adjusted.

CAUSE A build up of dirt around the boot may cause them to stick.

CORRECTION: Lubricate the boots on the steering box to prevent their sticking to the groove in the steering rod.

Prior to adjusting the rods when setting the toe-in, rotate the boots by hand to insure they are free. Spray boots with a silicone spray. When adjusting toe-in, make sure boots are not being twisted.

READ, INITIAL AND PASS ON

Service Manager	Parts Manager	Service Writer	Technician			