

FIAT SERVICE LETTER

SUBJECT: ELECTRICAL RELAY CLUSTER

VEHICLES: ALL 1978 X1/9 VEHICLES EQUIPPED WITH AIR CONDITIONING



SERIAL #: STARTING WITH SERIAL #74001

CONDITION: Possible reversed wiring at the two inline wire connectors located underneath the relay cluster (A) in the front luggage compartment.

CORRECTION: During PDI or when one of the above-mentioned vehicles is being serviced, check the two inline wire connectors underneath the relay cluster for proper wire connection.

The wire connections must be as follows:

Yellow and black to yellow and black (B)
Blue and black to blue and black (C)



READ, INITIAL AND PASS ON

Service Manager	Parts Manager	Service Writer	Technician