

FIAT SERVICE LETTER

SUBJECT: DOOR STRIKER PLATE

VEHICLES: X1/9

SERIAL NUMBER: 50549

CONDITION: Shifting of the door striker plate from its set position

CAUSE: Vibration due to road conditions

CORRECTION: In order to eliminate this occurrence, a new type gasket, which fits between the striker plate and the door pillar, is now being supplied on vehicles starting with the above serial number. Due to the coarseness of the material used in its production, the new gaskets will improve the set position of the striker plate to the door pillar.

PARTS INFORMATION: This new type gasket will be supplied as a replacement part for both early and late production vehicles. The part number of this gasket is #4367584.

READ, INITIAL AND PASS ON

Service Manager	Parts Manager	Service Writer	Technician			