

S.L. 100-16  
5-15-80

# **FIAT SERVICE LETTER**

REISSUE OF SERVICE LETTER

PREVIOUS SERVICE LETTER MISIDENTIFIED AS 100-15 DATED 5-15-80

SUBJECT: PULLEY SPLASH SHIELD

VEHICLES: 1979 X1/9 AND STRADA MODELS

REMINDER

Make sure the pulley splash shield, located underneath the engine compartment, is reinstalled whenever it is removed for repairs, especially after performing Service Improvement Campaigns No. 128 (X1/9 Charging System) and No. 129 (Strada Alternator Retrofit).

The pulley splash shield and other engine protection shields help prevent possible water and dirt infiltration into the engine compartment.

READ, INITIAL AND PASS ON

Service Manager	Parts Manager	Service Writer	Technician			