

FIAT SERVICE LETTER

SUBJECT: AXLE SHAFT
VEHICLES: 128 MODELS - X1/9

CONDITION: Under certain driving conditions, there may be an unusual noise through the drive train.

CAUSE: Vibration of the right side axle shaft

CORRECTION: In order to eliminate this vibration, the diameter of the axle shaft has been increased from 1.41" to 1.77". The new axle shaft is interchangeable with the earlier type shaft.

PARTS INFORMATION:
The part number of the new axle shaft is 4370722.

READ, INITIAL AND PASS ON

Service Manager	Parts Manager	Service Writer	Technician			